

Notice



- ☐ CORRECTION ☒ PRODUCTION CHANGE
☐ SERVICE FLASH ☐ ADD INFORMATION

FILE NO.

Please add this notice to the Service Manual listed below.

REVISION 0

Category: **COLOR TELEVISION**

Date: **NOVEMBER / 01 / 2011**

Model: **DP46861**

Effective from : Chassis No. **P46861-10**

Destination: **U.S.A. / CANADA**

REF : **No. SM780195-10**

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P46841-10. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P46841-10 used in Model DP46841 (SM780195).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

The are no changes.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The are no changes.

For parts or service contact:

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000